



# Customer Notification

<b>Notification #:</b>	20040903	<b>Revision:</b>	1.1	<b>Page:</b>	1 of 2
<b>Release Date:</b>	November 5, 2004				
<b>Effective Date:</b>	November 5, 2004				
<b>Notification Status:</b>	<input checked="" type="checkbox"/> Advisory	<input type="checkbox"/> Mandatory	<input type="checkbox"/> Announcement		
<b>Classification:</b>	<input checked="" type="checkbox"/> Firmware	<input type="checkbox"/> Hardware	<input type="checkbox"/> Policy/Procedure		
<b>Description:</b>	NexGen \$50 Firmware Versions - WBA				
<b>Hardware:</b>	WBA-10/11/12/13				
<b>Firmware Version:</b>	Multiple, (Reference list on page 2)				

**Correction:**

*Correction made to the Checksum of firmware WBA 10/11, ID-022/023.*

**Conditions:**

JCM engineering has released new firmware to our OEM partners for the USA NexGen \$50 release occurring on September 28, 2004. This firmware will be released by each OEM to the jurisdictional regulatory agencies for approval on their hardware platforms.

- Added NexGen fifty (\$50) USD recognition capabilities.
- Acceptance Security for the ten (\$10) USD has been improved.
- Acceptance Security for the fifty (\$50) USD has been improved. (2001 series)
- Acceptance Security for the one hundred (\$100) USD has been improved.
- During power recovery with a ticket in the path, if the WBA receives a reset command, the ticket will be stacked.
- Improved CPU run-away detection and recovery has been added.

**Notes:**

These firmware versions supercede all previous versions of JCM firmware. JCM recommends that all previous versions of firmware be upgraded to the 3.34-xxx series so that our customers can take advantage of the NexGen \$50, increased Acceptance Security, and power recovery / CPU run-away recovery features.



# Customer Notification

**Notification #:** 20040903      **Revision:** 1.1      **Page:** 2 of 2

**Release Date:** November 5, 2004

**Effective Date:** November 5, 2004

**Notification Status:**     Advisory       Mandatory       Announcement

**Classification:**         Firmware       Hardware       Policy/Procedure

**Description:**            NexGen \$50 Firmware Versions - WBA

**Hardware:**                WBA-10/11/12/13

**Firmware Version:**      Multiple, (Reference list on page 2)

### Software Reference List:

WBA 10/11:

ID	Version	Checksum
003	3.34-25	DBA9
022/023	3.34-03	7FCF
024	3.34-29	FF9F

WBA 12/13:

ID	Version	Checksum
ID-003	3.34-21i	1185
ID-003 (Aristocrat)	3-34-22i	11DB
ID-003 (Spielo)	3-34-23i	FA6F
ID-003 (Bally)	3.34-25i	2994
ID-0C3	3-34-09i	F1C3
ID-022/023	3-34-03i	5A07
ID-023B	3.34-04i	DF4E
ID-024	3.34-27	8999
ID-044	3.34-05i	FD8D
ID-044C	3.34-05i	144E