




Notification No.:	20090805	vision:	1.0	Page:	1 of 1
Release Date:	August 5 2009	Effective Date:	August 5, 2009		
Notification Status:	<input checked="" type="checkbox"/> Advisory	<input type="checkbox"/> Mandatory	<input type="checkbox"/> Announcement		
Classification:	<input type="checkbox"/> Firmware	<input checked="" type="checkbox"/> Hardware	<input type="checkbox"/> Policy/Procedure		
Description:	Plastic Cash Box Key Hole Cap P/N 900-100487R				
Hardware:	ICB Plastic Cashbox				
Interface:	N/A	Check Sum:	N/A		
Firmware Version(s):	N/A	CRC (seed = 0000):	N/A		

Conditions:
 JCM has received reports of plastic cashboxes being installed in the field without the Key Hole Cap, P/N 900-100487R (Fig. 1), installed in the unused lock hole. Note: JCM ships this part with every plastic cashbox.

Resolution:
 JCM recommends installation of the key hole cap for increased security. If you require additional security at your facility, VSR industries also offers a metal cash box plug in both Brass and Steel. (Fig. 2) LHW000610000010 - Plug w/nut, 3/16 Steel; LHW000610000017 - Plug w/nut, 3/16 Brass.






Fig. 1
Fig.2

Notes:
 The intent of this announcement is to accurately reflect information available at the time of this writing. This information can change or be modified at any time with no formal notification requirements. Please contact your local JCM Sales Representative or JCM Customer Service at (800) 683-7248 for additional information.